ग्रामपंचायत हरकुळ बुदुक

तालुका - कणकवलो, जिल्हा - सिंधुदुर्ग

ग्रामपंचायत कार्यालय, हरकुळ बुद्रृक दिनांक- १८/७/२००९



CERTIFICATE

It is certified that the building of S. S. P. M.'s College of Engineering at Harkul Budruk is completed and ready for use. The Grampanchayat has no objection to start the College in the building from the academic 2001.

प्राम्भवायत हरकूळ बुद्रक Grampanchayat Harkul Budruk

S. S. P. M. Kankavali

RUPESH N. TAWATE Consulting Lic. Civil Engineer

Planning, RCC Design, Interior Design, Perspective, Contour Survey, Road Sections, Plotting, Supervision, Estimates



Off.9881586506, 9766792555 Mob. No.: 9890565174



Email: rupeshtawate@gmail.com, rupeshtawate2017@gmail.com, rupesh_tawate@yahoo.co.in



At & Post Pawashi, Tal. Kudal, Dist. Sindhudurg-416520

05 2024 Ref.No.

Date: 08/07/2024

To,

Sub:- Stability Certificate for Educational Buildings at SSPM Engg. College Campus, Kankavali Ref:- Site Visit on 30 June 2024

Above Reference Site Visit and visual inspection is done for following buildings at SSPM Engg. College Campus,

Sr. No.	Particulars	Area (In Sqm)	Area (In Sqft)	Building Floors
1	Engineering college Phase -1	3528.06	37961.93	G+2floor
2	Engineering college Phase -2	3232.58	34782.56	G+2floor
3	Engineering college new building	5195.38	55902.29	Lower+G+2floor
4	Library	413.50	4449.26	Ground
5	Multipurpose Hall	693.71	7464.32	Ground
6	Canteen	407.29	4382.44	Ground+1
7	Incubation Center 1	535.43	5761.23	Ground+2
8	Incubation Center 2	353.56	3804.31	Ground
9	Club House	329.89	3549.62	Ground
10	Principal Bungalow	113.61	1222.44	Ground
11	Staff quarters	703.92	7574.18	Ground+2
12	Boys Hostel	2353.87	25327.64	Lower+G+1floor
13	Stage	256.94	2764.67	Ground
	Total	18117.74	194946.90	

Following observations are made while site inspection

- a. No major cracks found on structural members
- b. No considerable deterioration or damage found of structural members
- c. Any serious corrosion to steel members not noticed
- d. Nowhere major leakage or dampness noticed
- e. Deflection or change in shape or size in Structural members does not found.
- No settlement of Building noticed

Considering above observations and visual inspection I hereby certify that above mentioned buildings in SSPM Engg. College campus are found Safe for use for which they are designed.

Thanking You,

Yours

Name of Structural Engg. Rupesh Narayan Tawate

(Lic. No. STATE/R/2022/APL/04335)

-L/Al-AM 3035398 Chartered English Sindhudurg